

*Wyoming*

**Department of Workforce  
Services  
Office of Standards and  
Compliance  
Wyoming OSHA**

**Presented by:  
Mike Todd, CRM  
Administrator  
Wyoming OSHA Division**



Wyoming

## Well Servicing Fatality MAY 15<sup>TH</sup> 2013



Wyoming

# Don Carl Jordan



*Wyoming*

**1981 Hopper Gaxxta, Manufactured in Bakersfield, California. Third owner. Described as designed for shallow to medium depth well.**



# Personnel Involved

**Servicing Rig** - Contract employer providing well service, primarily to same well operator.

**Crew:**

Foreman

Derrick hand

Deck hand

Victim - New employee working as utility employee (“worm”).

**Witness**

Pump truck driver

**Owner** - A family owned and operated business, based in Worland, Wyoming.

# ACCIDENT SUMMARY


- Four man crew, lead by company owners son/Operator.
- Derrick Man decides to switch with deck hand to trip tube in.
- WORM/Victim - New fourth hand, no new employee orientation.
- Victim/OJT only. Anxious to prove himself.

## ACCIDENT SUMMARY

- Hopper service rig does not have a service or operators manual.
- Tongs are known as “Foster” tongs, slip over tubing, not around.
- Well is approximately 8500 feet, Crew normally does shallow coal bed methane (1200-1500 feet).
- Well still has a cellar basin and uses a non conventional pump system, not the normal “Horse head design”.
- Operator on site without “Tool pusher/owner/Dad”. Owner had recent medical problems. Operator working without benefit of Owner. \*

*Wyoming*

**Foster type, slip over tong system, with modified trailer hitch ball welded on tong end (red arrow), used to flip tongs.**





Wyoming

**Foster style tong with bent handle.**



## ACCIDENT SUMMARY

- Crew trips in well in about 2-3 hours, stopping for hot brakes several times.
- Crew stops to check Hydro Tarter as it was “Loud”.
- Operator summons pump truck, driving by, to pump out cistern while waiting.

## ACCIDENT SUMMARY

- Victim assists truck operator, crawling under the low position of deck to suction, as operator runs blocks.
- Operator begins running blocks up and down to cool brakes after trip in.
- Crew realizes they still have tube to run, however deck hand has removed the Foster tongs.

## ACCIDENT SUMMARY

- Deck hand, a smaller man, cannot get tongs back on tube.
- Operator sets brake with blocks about 30 feet above deck. Operator leaves hot breaks unattended.
- Victim is under deck, on stomach, suctioning cistern.

## ACCIDENT SUMMARY

- Truck driver hears high pitch whine, yells at crew.
- Blocks fall, striking operator and deck hand and subsequently deflects off of tongs, pushing island out.
- Falling blocks land on victim without benefit of adequate warning to egress from unsecured suspended load.

Wyoming

**Back of pump truck on site to suction fluid from well cellar. Driver was positioned here when blocks fell. Driver yelled as he heard load whine, then dove under truck.**



Wyoming

Deceased position (red arrow). Brake handle location (yellow arrow).



Wyoming

**Traveling blocks suspended by tuggger winch.**





Wyoming

**Operator station, brake handle (red arrow), linkage, lock mechanism (yellow arrow).**



Wyoming

Brake linkage lock assembly with spring below operators station.



Wyoming

**Draw works locking mechanism below operators deck.**



Wyoming

**Chain attached to blocks (red arrow) with tongs (yellow arrow) in background.**



Wyoming

**Suction hose to left of victim location at time of impact.**



Wyoming

**Arrow (yellow) indicates island board channel & island, pushed out by bails. Arrow (red) indicates deceased approximate position at time of impact.**



## Mechanical Investigation.

- Brake lever, linkage found to be in serviceable condition.
- Brake bands were not inspected on a routine basis due to draw work guards.
- Service rig, was not maintained in accordance with manufacturers guide as the company did not have such manuals.
- Brake band pads were within factory tolerances however had many missing retainer bolts.
- Island floor deck insert was not secured in place.

Wyoming


## WY-OSHA observes draw works & brake system investigation.






Wyoming

**Draw works, brake bands with missing nut visible (over 17 missing). Front hydro tarter.**



*Wyoming*

**Old brake bands, 1" Plus. Note hard pads (RED) and soft pads (YELLOW). Drum (GREEN).**



Wyoming

**Draw works, operators side with brake band off.**



## Subsequent Supporting Investigation

- In an effort to establish root cause analysis, CSHO interviewed widow to obtain former employee list.
- Former employee interviews indicate a similar incident had occurred in early 2013 on the same well, with primarily the same crew and operator.
- Service rig owner was on site during this incident.
- CSHO established through extensive interviews of former employees a pattern of inadequate safety, training and preparation of employees and equipment.

## Subsequent supporting investigation

- CSHO re-interviewed crew and owner. Employees did acknowledge the blocks had dropped previously.
- Operator acknowledged incident did occur.
- CSHO established Winchester Well Service failed to take adequate precautions to prevent hazards which they knew, or should have known, were pre-existing.

## ROOT CAUSE

- Operator left his post at the operator's station leaving brake lever unattended, with prior knowledge that the brake system would "creep" if under load as hot brakes cooled.
- Operator broke routine allowing inexperienced victim under suspended load while still tripping tubing in.
- Operator and Owner failed to conduct near miss investigation and provide corrective action on equipment after near miss in early 2013.
- **Incident was predictable and preventable.**

*Wyoming*

**Department of Workforce  
Services  
Office of Standards and  
Compliance  
Wyoming OSHA**

**Presented by:  
Mike Todd, CRM  
Administrator  
Wyoming OSHA Division**

